

2023 Nissan Altima

Was this vehicle involved in a collision?

NO

YES

Date: **Nov 25, 2024**
RO: **2040**
VIN: **1N4BL4EV9AB123456**

Company: **Your ADAS Company**
Estimator: **Jim Smith**
Location: **Longview, Texas**

3 REQUIRED STEERING
OPERATIONS

2 REQUIRED ADAS
OPERATIONS

2 REQUIRED SAFETY
OPERATIONS

Equipped ADAS Features

1. Speed sensitive power steering
2. Electric power-assist steering system
3. Brake assist system
4. Trunk
5. High Beam Assist (HBA) auto high-beam headlights
6. Driver front impact airbag
7. Seat mounted side impact driver airbag
8. Curtain first and second-row overhead airbags
9. Passenger front impact airbag
10. Seat mounted side impact front passenger airbag
11. Airbag occupancy sensor
12. Driver and passenger side knee airbags
13. Rear side impact airbags
14. Front and rear seatbelt pretensioners
15. Intelligent Cruise Control (ICC) w/Full Speed Range and Hold
16. ProPILOT Assist hands-on cruise control
17. Front mounted camera
18. Right side camera
19. Tire Pressure Monitoring System tire specific low air pressure warning
20. Rear parking sensors
21. Intelligent Lane Intervention (I-LI)
22. Blind Spot Warning (BSW)
23. Intelligent Forward Collision Warning w/Automatic Emergency Braking (AEB)
24. Rear Automatic Braking (RAB) collision mitigation
25. Automatic Emergency Braking with Pedestrian Detection
26. Traffic Sign Recognition (TSR)
27. 4 seatbelt pre-tensioners
28. Left side camera
29. RearView Monitor rear mounted camera
30. aerial view camera

STEERING OPERATIONS

Fuel Requirement Before a Calibration ⓘ

Fuel Requirement

Estimate Location

The OEM service information for a 2023 Nissan Altima says that a required operation must be performed on the Fuel Requirement Before a Calibration after the following repairs are done:

- The Fuel Tank Must Be Full Before Performing the Distance Sensor Alignment

OEM Procedure Requirements and Instructions



[Distance Sensor Alignment Fuel Requirement](#)



[Lane Camera Adjustment Fuel Requirement](#)

Wheel Alignment ⓘ

Wheel Alignment

Estimate Location

The OEM service information for a 2023 Nissan Altima says that a required operation must be performed on the Wheel Alignment after the following repairs are done:

- A 4-wheel vehicle alignment must be performed before proceeding with distance sensor alignment procedure

OEM Procedure Requirements and Instructions



[Alignment Required For Distance Sensor](#)

Steering ⓘ

Calibration Type: Static

Adjustment of Steering Angle Sensor Neutral Position

Estimate Location

The OEM service information for a 2023 Nissan Altima says that a required operation must be performed on the Steering after the following repairs are done:

- Steering Angle Sensor Reset is Required After A Wheel Alignment

OEM Procedure Requirements and Instructions



[Steering Angle Sensor Reset](#)



[OEM Procedure](#)

ADAS OPERATIONS

Front Radar ⓘ

Calibration Type: Static

Distance Sensor Alignment, Work Procedure

Estimate Location

The OEM service information for a 2023 Nissan Altima says that a required operation must be performed on the Front Radar after the following repairs are done:

- Front bumper is Installed(line number 3).
- Grille assy is Replaced(line number 14).
- Grille assy is Replaced(line number 18).

OEM Procedure Requirements and Instructions



[Required Radar Calibration Post-Repair](#)



[Outline of Radar Alignment Procedure](#)

Around View Monitoring ⓘ

Calibration Type: Static

360 Degree Camera Calibration

Estimate Location

The OEM service information for a 2023 Nissan Altima says that a required operation must be performed on the Around View Monitoring after the following repairs are done:

- Grille assy is Replaced(line number 14).
- Grille assy is Replaced(line number 18).

OEM Procedure Requirements and Instructions



[Calibration of Around View Monitor](#)



[How to perform the Procedure](#)

SAFETY OPERATIONS

Seatbelts and Post Collision Safety Inspections (SRS, Steering Columns, etc.)



Calibration Type: Static

Seat Belt - Inspection, Preliminary Checks, Seat Belt Retractor On-Vehicle Check, Seat Belt Retractor Off-Vehicle Check

Estimate Location

The OEM service information for a 2023 Nissan Altima says that a required operation must be performed on the Seatbelts and Post Collision Safety Inspections (SRS, Steering Columns, etc.) after the following repairs are done:

- Vehicle is involved in a collision

OEM Procedure Requirements and Instructions



[OEM Requirement](#)



[OEM Procedure](#)

Vehicle Diagnostics ⓘ

Prescan/Postscan

Estimate Location

The OEM service information for a 2023 Nissan Altima says that a required operation must be performed on the Vehicle Diagnostics after the following repairs are done:

- Vehicle is involved in a collision

OEM Procedure Requirements and Instructions



[OEM Requirement](#)

Total: \$0

Disclaimer

This report is generated using OEM and Third Party service information. All equipped features installed on the vehicle and accuracy of this report should be verified by a qualified technician onsite. SourceADAS is not responsible for any unverified information or misprints in OEM documentation.